

Oil Field Environmental Incident Summary

Incident: 20150803195616 **Date/Time of Notice:** 08/03/2015 19:56

Responsible Party: MUREX PETROLEUM CORPORATION

Well Operator: MUREX PETROLEUM CORPORATION

Well Name: RICK CLAIR 25-36H

Field Name: STANLEY

Well File #: 16930

Date Incident: 8/3/2015

Time Incident: 12:30

Facility ID Number:

County: MOUNTRAIL

Twp: 155

Rng: 91

Sec: 36

Qtr: SE SE

Location Description:

Submitted By: William Jansky

Received By:

Contact Person: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.5	Barrels	0.5	Barrels	0.5	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/3/2016

Clean Up Concluded: 8/2/2016

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Stuffing box components replaced. Bioremediation for impacted soil.

Wastes Disposal Location: PDI

Agencies Involved:

Updates

Date: 8/4/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a stuffing box leak, remained on location according to the report. NDIC retains oversight.